

Rpt. 8

DISCLOSED
SECTION
No.

DISCLOSED
SECTION
No. 686
Port Received London
No. 14118
First Date 19 Last Date 19

Date of writing Report
Survey held at
When handed in at Local Office
No. of Visits
First Date 19 Last Date 19

REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B. 91189 on the Iron or Steel S.S. "Ruscini"
Built at By Whom
Owners' address (If not already in R.B.)
Managers Port of Registry
Surveyed Afloat or in Drydock Name of Dock Date of last examn. in Drydock
Tons gross 7269
Year 1943 Month

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. Port
To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS Date of Special and of Drydocking Surveys, etc.	Machinery

Give dates and references to any letters relating to this Report

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined Freeboard as marked on ship and now verified ft. ins
Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? Is Classification Certificate required? If so, to be sent to
If so, is the Report sent now, or when will it be sent? Has Interim Certificate been issued?

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS
State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

Surveyor to Lloyd's Register of Shipping

Date of Committee FRIDAY 26 MAY 1961
Minute Class withdrawn at. Bonus agreed 5:61
GENERAL COMMITTEE Thursday 135 June 1961
Classing Committee's decision confirmed.
50m,4,59 T. (MADE AND PRINTED IN ENGLAND)

612306-012314-0118

© 2021

Lloyd's Register Foundation