

Bethlehem Fairfield Shipyard Inc., Baltimore Md.

Chief Ship Surveyor

Received from Chief Ship Surveyor

6 JAN 1949

NAME S.S. "MARABANK" Ex. REPORT Lon. No. 117120  
"SAMOUSE"

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/42.)

This Liberty type vessel was built in 1943 and classed with the American Bureau of Shipping.

Classification with this Society is desired.

The vessel holds the Notation 100A.1. (Classification Contemplated) Examined 4.48."

These Notations are subject to permanent repairs to indented sheerstrake plate No.2. (s.s.) at the first convenient opportunity.

The greater part of the Special Survey for Classification has been held, for particulars see previous endorsements.

ACTION is deferred for Completion of Special Survey.

The LONDON Surveyors in a First Entry Report in accordance with Circular 1871, report 8.48, the scantlings and arrangements verified, as far as now examined.

IT IS SUBMITTED ACTION continue to be DEFERRED for Completion of SPECIAL SURVEY for CLASSIFICATION.

now. Subject.

E.M.D.  
4/1/49.  
L.M.B.



© 2021

Lloyd's Register  
Foundation

012306-012314-0145