

LE

S.S. "WAR BRAHMIN".

It is submitted the Ministry of Shipping should be informed in reply to their letter of the 7th instant that the Society's Surveyors at Greenock, under whose inspection the vessel was built, have been communicated with, and they state "With regard to the deck of oil fuel bunkers the "bunkers were tested while the vessel was being built on the ways "with a head of water of twelve feet as required by the Rules, "and riveting and caulking were found to be quite tight and "satisfactory." The Surveyors further observed that it is not stated at what part of the deck the rivets were renewed, at Port of Spain.

The Ministry of Shipping should further be informed that the Society has no Surveyor stationed in Trinidad, and it is suggested that the matter should be left over for the present and a special examination made of the vessel upon her arrival at a home port.

ML *C.J.* 15.4.20



© 2021

Lloyd's Register
Foundation

012315-012323-0224