

Received from Chief Ship Surveyor

13 SEP 1954

SHIP'S NAME

"S A T A"

REPORT

Cff.

No. 58869

GB

Outstanding Conditions of Class:

Subject to permanent repairs to buckled stem and stem plating, etc. by 3,54 and to indented bottom plating, etc. (p & s) by next Special Survey.

Endorsement of Class (B) (~~As before~~ None)

Nature of Present Survey: (Afloat and in dry dock)

Further deferment of repairs to **BUCKLED** stem and stem plating as above.

Recommendation:

SUBMITTED record of docking 8,54 be assigned as recommended, subject to permanent repairs to buckled stem and stem plating, etc. and to indented bottom plating, etc. (p & s) by the Special Survey.

8,54 Cff. Subject Amended.

13.9.54.



© 2021

Lloyd's Register
Foundation

012346-012357-0196