



X

Esso France

17, BATTERY PLACE,

NEW YORK 4, N. Y.

April 21, 1948

RECEIVED

15 MAY 1948

Dear Mr. Sladden:

S/S ESSO FRANCE ex GRAVENCHON
N. Yk. 47899

Referring to the inquiry contained in your letter of the 5th February last, the Surveyors state that the thickness of the flat plate keel is .84" and not .44" which was incorrectly reported. They also confirm that 2" diameter Improved High Lift is correct for these boilers.

Yours faithfully,

R. J. Sladden, Esq.

LONDON



© 2021

Lloyd's Register
Foundation

012346-012357-0235

How 12/3

Noted
Dr. 6.5.48.

H
R.S.

V/S Hans 23/4 mch 1948

Noted
R.S.



© 2021

Lloyd's Register
Foundation

The
Dea
of
Ste
boil
Octo
on t
show
of t
they
rais
were
are
boil
and
Give
each
high
or d
1.5/
ask
due
if t
New
safe
safe
fitt
safe
of th
as th
clean
drydd