

4E

MODEC 1250

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....


S NAME..... SUTHER-NESS..... REPORT..... Mil. No. 8418.....

MBS due 8.58 now partly held.

Some combustion chamber back plates ^{stays} found wasted
and the Surveyor recommends the defective combustion
chamber back plates ^{stays} be renewed before the end of 1.59

IT IS SUBMITTED that this vessel is eligible
for the record of MBS 11.58 on completion of the survey,
subject as recommended.

To complete MBS The safety valves to be adjsuted
and the condition of class dealt with.



2021
4.12.58.

012358-012364-0020

Lloyd's Register
Foundation