

Ship's name "SOUTHERN GAMBLER"

Port

OSL

No. 9607.

Last survey date 26/10/62.

Class is subject to:-

Metallock repairs (7.61) to stern tube and outer end in way of nut being specially examined at the next dry docking.

Docking.

MBS due 12.62. Now held.

SPS due 9.62. Now held.

ES due 6.62. Now held.

SRL: The above item dealt with and found to continue efficient but the Surveyor recommends that a further special examination be made at the next dry docking. But, it is submitted that in view of the present and previous satisfactory examinations made of the Metallock repairs that the item be deleted from the list and noted in the SRL Appendix.

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh records of MBS 10.62, ES 10.62 and SPS 10.62, without special condition.

SRL APPENDIX NOTE.

19.11.62.

Insert the following:- "Metallock repairs to stern tube and outer end in way of nut".

NOTE. The Oslo Surveyor should be informed that, as regards the Metallock repairs to the stern tube end in way of nut, etc. in view of the present and previous satisfactory examinations made of the repairs that the item is being deleted from the list and noted in the SRL

Appendix. *an amended S.C. should be added during the reference to this item*

CERTIFICATE WRITTEN

End. E.3

012358-012364-0148

Lloyd's Register
Foundation