



by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

EL'S NAME 'SOYA - MARGARETA' REPORT Mmo. No. 3104
Nwc. 108525


Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Oil Engine 2 SCDA

6 Cyl. 28 3/8" - 47 1/2".

New MN 1200.



~~If Boilers fitted with forced draught-~~

Tail Shaft. If fitted with a continuous liner Yes.

If fitted with an outside gland of approved type No.

The torsional vibration characteristics of the main propelling machinery were approved in the Secretary's letter of 5.7.51 for a service speed of 110 RPM.

Similar calculations for the 200 KW generator sets were approved in the Secretary's letter of 12.7.49 for a service speed of 350 RPM provided torsionograph records be taken.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed +LMC 5.52.

Carrying Petroleum in Bulk.

2 DB 180 lb.

Note for SRL. Exhaust gas economiser to be examined at each DBS.

