



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

25 Ballindamm, Hamburg 1

Telegrams: Surveyors, Hamburg

RECEIVED

Telephone: No. 33 35 39
33 88 08

- 6 NOV 1951

2nd November, 1951.

Reference

2977/51/A.

Dear Sir,

Ans.

Hamburg Report Nos. 1449/50.

We are in receipt of your letter of the 19th September, reference Classn.C., concerning the above reports in respect of Lübecker Maschinenbau-Gesellschaft boilers Nos. 1441/2.

The plate thicknesses by measurement on the site are as reported in each case, with the exception that in Rpt.No.1449 on boiler No.1441 the combustion chamber back plate should read 16 mm. The typing error in this case is regretted.

The plate thicknesses, therefore, are correct as reported in the other instance and are as follows: -

End plates in steam space	26 mm		24 on plan approved.
Tube plate front	26 mm		
Back comb.chamber plates	16 mm		
Front plate at bottom	26 mm		
Back plate at bottom	26 mm.		

The Secretary,
London.

Yours faithfully,

Alfred

012370-012376-0032

Lloyd's Register
Foundation

CLASSIFICATION

C

Handwritten signature

Noted

DM 6/11/51



asn.c.

© 2021

Lloyd's Register
Foundation