

19th September, 1951.

Dear Sirs,


ssn.C.

Hamburg Report No.1449/50

With reference to the above reports covering Lübecker Masch.-Gesell. Boilers Nos.1441/2, I shall be glad if you will confirm the corrections listed below.

|                           |       |         |       |             |
|---------------------------|-------|---------|-------|-------------|
| End plates in steam space | 24mms | and not | 26mms | as reported |
| Tube plate front          | 24mms | " "     | 26mms | " "         |
| Back comb. chamber plates | 16mms | " "     | 18mms | " "         |
| Front plate at bottom     | 24mms | " "     | 26mms | " "         |
| Back plate at bottom      | 24mms | " "     | 26mms | " "         |

Yours faithfully,

  
pro Clerk to the  
Classification Committee.

The Surveyors,  
HAMBURG.



© 2021

Lloyd's Register  
Foundation  
012370-012376-0034