



damaged, dressed up.  
Pitch of blades checked and found satisfactory.  
Propeller replaced in good order.

Boiler Survey:

Main Boiler examined internally and externally over all parts, together with doors and fastenings, and found satisfactory.  
All Boiler mountings opened up, valves ground in, examined, found or placed in good order, glands repacked and covers rejoined.  
Steam smothering gear under boiler examined.  
Oil fuel system examined.

It was stated the adjusting of the Boiler Safety Valve will be dealt with and examined by the Marine Superintendent Engineer representing the Owners, at a later date, and this office will be advised when Valves are satisfactorily adjusted.

*W.D. Wardle*

200



© 2021

Lloyd's Register  
Foundation