

REPORT of SURVEY for REPAIRS, &c.

of writing Report 9/4/38 When handed in at Local Office 9/4/38 Port of HULL
Survey held at HULL Date, First Survey 10/3/38 Last Survey 17/3/38
Book. (No. of Visits 3)

551 on the Wood, Iron or Steel ROCKBREAKER
Tonnage: 251 Built at BEVERLEY By whom COOK WELTON & GEMMELL When 1938 - 3
ROSS 236 Owners JAMES DREDGING TOWAGE & TRANSPORT Owners' Address
NDER DK. 169 Managers Port belonging to LONDON

urveyed Afloat or in Dry Dock? DRY DOCK Name of Dock UNION DRY DOCK. Destined Voyage SOUTHAMPTON (W. TOW.)
B=Cell DBorDBa feet; uE&B feet; f feet
al capacity tons. FPT tons; APT tons; MT feet tons.

st Report, No. F.E. REPORT Port HULL
ENCLOSED.

Radical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined NOT REQUIRED.
Was a damage report made by anyone else? If so, by whom? UNDERWATERS SURVEYOR.

PAIRS, OR EXAMINATION AS PER RULE, FOR COLLISION DAMAGE REPAIR.
Damage stated to have been sustained by colliding with an object unknown during the unlash passage down the River Hull from Beverley to Hull on 28th February 1938.
Damage sustained to No 4 plate of strake below sheerstrake on starboard side (indented)
Repair now done: No 4 plate of strake (D) below sheerstrake starboard renewed, and repaired and has been tested on completion of repair.

PRIMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed	/							
Removed and Fairied or Repaired								
Fairied or Repaired in place								

State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
State if Tanks now tested	Dbng. Plates under Sounding Pipes	(State if on Felt.)
Bulkheads	Engine Room Skylights	When put on, Month Year
Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Boats
Cement or Asphalt (State which.)	Oil Bunkers	Masts, Yards, &c.
Rudder	Scuppers	Condition, how ascertained
Steering gear and its connections	Cargo Hatchways	(State if wedges removed)
Windlass	Hatches	Sails
Have pumps now been examined and found efficient?	Planking of Wood Vessels	Equipment letter
Have Sluice Valves now been examined and found efficient?	Caulking ditto	Anchors, No. of
Have Watertight Doors now been examined and found efficient?	Treenails ditto	Chain Locker
Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Cables (State if now ranged)
	Transoms Pointers, & Crutches ditto	length mean diamr.
	Timbers of Frame at openings ditto	(on board)
	Ditto Ditto at other places ditto	Rule length size
	Stringers, Clamps & Shells ditto	Hawser & Warps
	Salting ditto	Standing and Running Rigging
	(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24."
For the information of the Committee.

Survey Fee (per Section 20) £ : ✓ : Fees applied for, 19
Special Damage or Repair Fee (if any) £ : ✓ : Received by me, 19
Selling Expenses (if chargeable) £ : ✓ :
and Surveyor's Fee (if any) £ : ✓ :
Surveyor to Lloyd's Register of Shipping.

Committee's Minute
Character Assigned
TUE 14 NOV 1938
See Hull 78. 48776
Lloyd's Register Foundation
012423-012430-0329