

N/N LAURENTINO

11:2 APR 1948

Rpt. 8

(Received at London Office)

No. 4533

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 7th April 1948 When handed in at Local Office 19

Port of LISBON

Survey held at LISBON

Date, First Survey 13th December Last Survey 31st March 1948

No. in Reg. Book

(No. of Visits 20)

Suppl. 4138 on the ~~Wood~~ Steel S/Trawler "LAURENTINO" ex Jan de Waale

YEAR. MONTH.

TONNAGE: Built at Selby By whom Cochrane & Sons Ld. When 1925 2mo.

GROSS 342 Owners Cia. de Pesca de Mocambique Owners' Address Lourenço Marques

UNDER DK. 300 Managers Cia. de Pesca de Mocambique. Port belonging to Lourenço Marques

NET 139 Surveyed Afloat or in Dry Dock? Both Name of Dock No. 4 DD. Destined Voyage

U/D Bor/DBa feet; uE&B feet; f feet }
Tons. FPT tons; APT tons; MT feet tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N. B., if any).
+100A1	+LMC8.46
stm. Trawler	TS5.46
2.10 10.47	CL
SS Ant. 8.46	
Reclassified 8.46	

Only alterations in the existing records of tanks should be inserted.

B. — All alterations in the existing records should be underlined.

Report, No. 24433 Port edit

Special Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to be completed. The surveys should be summarised. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of anchors or chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he has offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR CONDITION AND ALTERATIONS.

Work done:— Vessel placed in drydock, bottom and rudder cleaned, examined and recoated. Decks, casings, framings, hatches, ventilators, windlass, steering gear and general equipment examined. Minor riveting and caulking overhauled and made good.

Alterations.
The existing deck house abaft the ER. comprising galley and entrance to accommodation below deck, is now been extended aft to form a saloon. This deckhouse, 15'x9'6" and 7' high, of 9 mm plating suitably stiffened and secured to the deck, is covered by a wood deck extending to the ship's sides. The deckbeams are supported by stanchions from the main deck at ship's sides and are fitted with tie plates. A pair of 4 1/2" diam. davits is fitted each side, abreast this new deckhouse, carrying lifeboats for 22 and 19 persons respectively, housed on the new boat deck. The original saloon immediately

MATERIALS OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								(p.t.o.)
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y. M. (State if on Felt.)
Plating good	part exmd. good	good	When fitted, Month Year
Planking of Decks "	Ceiling "	Coal Bunkers, Openings, Covers, &c. —	Boats good
Framings "	Cement or Asphalt "	Oil Bunkers —	Masts, Vards, &c. "
Rivets & Fastenings "	Rudder good	Scuppers —	Condition, how ascertained from deck (State if wedges removed.)
Side Plating "	Steering gear and its connections "	Cargo Hatchways good	Equipment letter O
Windows in way of sidelights —	Windlass "	Hatches "	Anchors, No. of 1B 1K
Transverse Frames —	Have pumps been examined and found efficient? —	Planking —	Cables (State if now ranged) no
Longitudinals —	Have Sluice Valves been examined and found efficient? —	Caulking —	length — mean diamr. — (on board)
Transverses —	Have Watertight Doors been examined and found efficient? —	Treenails —	Rule length — size 1 1/2"
Stanchions —	Have Watertight Doors been examined and found efficient? —	Breasthooks & Stems —	Chain Locker —
Bottom Plating —	Have Ventilators and their Coamings been examined and found efficient? yes	Transoms, Pointers & Crutches —	Hawsers & Warps good
Have the Tanks been examined internally? no	Air and Sounding Pipes —	Timbers of Frame at openings — or other places —	Standing and Running Rigging "
Have the Tanks been tested? no	Doubling Plates under Sounding Pipes —	Sringers, Clamps & Shelves —	Sails —
		Saling (State if examined.) —	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— to remain as classed in the Register Book without fresh record of Survey* to remain as classed and to have record of survey, 1,38, or to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38.

This vessel is eligible in my opinion to remain as classed with fresh record of survey 3,48 subject to the bower anchor and 15 fms. of cable being supplied at the earliest opportunity,

Survey Fee (per Section 29) DD	Ex. 300 \$00	Fees applied for, 7/4 1948
Special Damage or Repair Fee (if any) ALT ^{MS}	4.000 \$00	Received by me, 7/4 1948
Travelling Expenses (if chargeable) PART SUNDAY FEE	150 \$00	
Second Surveyor's Fee (if any)	150 \$00	

Committee's Minute

WED. 5 MAY 1948

Character Assigned

Deferred for Equipment. Write his. 3.48 his. 1.3.48 B.S. 3.48

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

012431-012438-0233

Is Certificate required? If so, to be sent to

