

26th May, 1949.

by who

TELEPHONE: 31240.



Lloyd's Register of Shipping,

RECEIVED

4 NOV 1949

64/68, Duesternbrooker Weg,
23, Duppelstrasse,

Kiel, 31st October, 1949

ANSD.....

The Secretary
Lloyd's Register of Shipping
London

*n/s Hel 1/49
Reclass
D
Copied*

Dear Sir,

In connection with the Reports 13 for the M/T "RINGFJELL", "SIREFJELL", and "HAUGFJELL" despatched to-day, it should be noted that part of the wiring of these three vessels is not in compliance with the Rules. This matter, as you are aware, is already in hand, and it is anticipated that the latter vessel will arrive in Kiel next week and will be dealt with as required. It is understood that the owners are also arranging for that part of the electrical installation which does not comply in the case of the "RINGFJELL" to be dealt with as soon as possible.

We are, dear Sir,

Yours faithfully,
For The Surveyors

W. Bassett
Surveyor.

*No report
received
as at
3/2/50*



© 2021

Lloyd's Register
Foundation

012439-012445-0300

012439-012445-0301

Referred to the Chief ~~Engineer~~ Surveyor.

HB.

noia
B.C.
7/11/49



© 2021

Lloyd's Register
Foundation

