

COPY.

# Lloyd's Register of Shipping.



Port KINGSTON, JAMAICA, B.W.I.

16th April, 1940.

This is to Certify that

EDGAR WATSON,

the undersigned Surveyor to this Society did at the request of Messrs. R.S. Gamble & Son, Lloyd's Agents at this Port and the Owners, survey the M.V. "KROSSFONN", 9323 tons of Stavanger, it being reported that the temporary repairs to the shell plating in No.2 Port Wing tank, were leaking.

For further particulars see log books.

On examination afloat at Kingston, Jamaica, B.W.I., on the 15th instant:-

FOUND

Cement box, on the bilge strake of shell plating in No.2 Port Wing tank, leaking.

RECOMMENDED

As a further temporary repair stop leaks and increase the size of the cement box.

... (Sgd) ... EDGAR WATSON .....  
Surveyor to Lloyd's Register of Shipping.

Fee:- £4. 4. 0.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."