

Rpt. 8

Port of HULL.

No. 66315

Date of writing Report 31/10/60

When handed in at Local Office

Received London

Survey held at HULL.

No. of Visits 1

First Date and 19

Last Date 19/10/19 60

REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

60819

on the Iron or Steel

SS

Tug "FENMAN"

Tons gross 54

Year 1943

Month 12

Built at Hessle

By Whom Richard Dunston, Ltd.

When 1943

Owners United Towing Co. Ltd.

Owners' address (If not already in R.B.)

Managers

Port of Registry Hull

Surveyed Afloat or in Drydock Drydock

Name of Dock Drypool

Date of last examn. in Drydock 19/10/60

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 66049

Port

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Give dates and references to any letters relating to this Report

SHIP'S CLASS  
Date of Special and of Drydocking Surveys, etc.

Machinery

Al tug Harbour and River  
service 7,60

LMC 2,59

MBS 7,60

TSOG 7,58

sps 8,55

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified

ft ins

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR

DOCKING

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship?

Yes

Is Classification Certificate required? If so, to be sent to

If so, is the Report sent now, or when will it be sent?

Now

Has Interim Certificate been issued?

Yes

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

This vessel so far as now seen is eligible in my opinion to remain as classed and have fresh record of D.S. 10,60.

Surveyor to Lloyd's Register of Shipping

Date of Committee

Minute

DS 10.60

TS 10.60

30m.4,57 T.



© 2021

Lloyd's Register Foundation

012460-012472-0047

CLR



PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR:

## SURVEY

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

The present condition of the following parts in so far as examined is to be reported:—

...See Below.

REMARKS, REPAIRS, Etc. (Contd.)

Date when A/c. Rendered

© 2021

100 (y any) 40m,4,5  
Lloyd's Register  
Rendered  
Foundation