

"TSINAN"


It is submitted the Hong Kong Surveyors be informed that with regards to the machinery of this vessel the requirement of 28 of the Rules should be carried out, but that the examination of the boilers and screwshaft as reported in their Report 10 of 12. 10. 51 could be accepted towards the Classification survey. The scantlings would however require to be checked with the approved plans.

Chang

31. 10. 51.

Saw

XR-J.



© 2021

Lloyd's Register
Foundation

012473-012482-0201