

NAME "SAN EDUARDO" REPORT 11325 No.

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in hundredths of an inch.

	AMIDSHIP.					FORWARD.					AFT.					REMARKS.
	Original Thickness	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.	
L	30	-	-	-	-	34	-	-	-	-	30	-	-	-	-	
K	30	-	-	-	-	34	-	-	-	-	30	-	-	-	-	
J	62	60	60	020	020	40	40	40	-	-	40	40	40	-	-	
H	50	45	45	050	050	40	40	425	-	-	40	35	35	050	050	
G	50	45	475	050	025	40	45	45	-	-	40	42	35	-	050	
F	50	50	425	-	075	40	40	40	-	-	40	40	45	-	-	
E	50	45	45	050	050	40	425	45	-	-	40	35	35	050	050	Cement found
D	50	Cement	Cement)		-	-	-	-	-	40	40	35	-	050	adhering
C	50				40	375	375	025	025	40	35	425	025	-	satisfactorily	
B	50				-	-	-	-	-	40	40	40	-	-	& not removed	
A	50				40	40	45	-	-	40	42	40	-	-		
-	68)		60	-	-	-	-	60	-	-	-	-	

Drillings at ends to be made in the vicinity of the peak bulkheads.