

# Docking Survey & SRL repairs.

Received from Chief Ship Surveyor

13 OCT 1960

HIP'S NAME "GARDVIK" REPORT Bgn. No. 4761

A

Outstanding Conditions of Class: SUBJECT to a bower anchor and 15 fathoms of chain cable (supplied Rotterdam) being verified with certificate at the earliest opportunity, and to shell plating (p.s) in way No.1 hold (wastage) being examined and dealt with as necessary on completion of the present voyage and by 9,60.

R.L. Appendix. (AS BEFORE OR None)

ature of Present Survey: (As before and in dry dock)

Docking: Wear and tear repairs including deferred items as above.  
Alterations - Rudder area increased by fitting strip on after edge.  
Equipment - Verification of a bower anchor and 15 fathoms of chain cable.

Recommendation: SUBMITTED record of DS 9,60 be assigned, without special conditions.

DS 9,60 without.

C.S.S. Records Dept.  
to note.

IT IS FURTHER SUBMITTED the Surveyors be advised it is concluded that copies of certificates of bower anchor and 15 fathoms of chain cable were endorsed, but confirmation is desired.

*in letter dated 12/10/60*

*4761*



© 2019  
30/9/60

Lloyd's Register  
Foundation

Blk (new)

port side NO. 1 hold.

012483-012492-0019