

4 E

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SELS NAME

"RAHUMAN I"

REPORT

Gls. 67812  
 Ips. No. 111662  
 Cbo. 2435a

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

e of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

The machinery of this vessel was not constructed in accordance with the requirements of the Rules, but under the Society's supervision and in accordance with M.O.T. specification.

The boiler has been constructed under Special Survey in accordance with approved plan and M.O.T. specification. The machinery and boiler have been installed under the supervision of the Society's Surveyors and in accordance with the terms of the specification.

Classification with this Society is now desired, and the vessel has been examined in dry dock and the requirements of LMC and TS carried out.

IT IS SUBMITTED that this vessel is eligible  
 for the record LMC 6.50  
 S OG 3.50

### Particulars for Register Book

Compound

10 $\frac{1}{2}$ " x 22" - 14"

1 SB 120 lb.

HS 212 sq.ft.

MN 15.

*End* *L.Y.*  
 10. 10. 50.



© 2021

Lloyd's Register  
 Foundation

012501-012507-0173