

Received from Chief Ship Surveyor 17 FEB 1954

SHIP'S NAME "DAUNTLESS STAR"
JD.

REPORT Hfx. No. 6672

Outstanding Conditions of Class:

Subject to permanent repairs to indented stem plating, etc. (p.s.) by next drydocking.

Endorsement of Class (B) ~~(As per former)~~ None)

Nature of Present Survey: ~~(As per former)~~ in dry dock)

Examination in drydock.

Recommendation:

SUBMITTED record of docking 1,54 be assigned as recommended, subject as above.


1,54 Hfx. Subject.

IT IS FURTHER SUBMITTED the Surveyors be referred to their report No. 6547 and be informed it is concluded that the indented stem plating, etc. continues efficient and that no alterations are required to the conditions of class.

Amend R. B. A.

g in red.

[Signature]



012501-012507-0205

Lloyd's Register
Foundation