

Rpt. 8

REPORT OF SHIP SURVEYS AND REPAIRS

Received London

23. MAY 1966

Ship's Name SS/MS "ST. AGNES". Gross tons 226.
L.R. 530540
Is there a rpt. 9? No. Port FALMOUTH. Rpt. No. 14871.
No. of visits One. First date and 8 Last date 13.5.66.
Interim Cert. issued & copy herewith? Yes. Damage rpt. issued & copy herewith? No. Last rpt. (H.Q. only) FA 14851
Date of completing rpt. 13.5.66. Surveyed at, if different from Port above -
Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D. -
Has a Load Line Survey been held? No. Freeboard Marks verified -

State which additional Rpt. 8 is attached: ~~(Cont)~~; ~~(PS)~~; ~~(DR)~~; (EQ); ~~(Hig)~~

Survey fees	Damage fee	Expenses
-	-	-
No Fee Charged.		S.A. fee -

I have surveyed the above ship in accordance with the Rules for replacement of Equipment

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

CONDITION OF CLASS.

Equipment. 2 lengths of Anchor Chain cable and connecting shackles now supplied and fitted.

It is submitted that this item be deleted from the S.R.List.

I recommend that this ship remain as classed with/without fresh record of dry docking and without conditions regarding the 2 lengths of Anchor Chain Cable.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

TUESDAY 7 - JUN 1966

Minute

as now. without fresh record
SS 3. 66

Surveyor to Lloyd's Register of Shipping

FOR CHAIRMAN
CLASSN. CTTEE

ALSO FOR
SPL FOR
RECORDS
POSTING
HEADER
CERT

23 JUN 1966

012814-012521-0145 1/2

Ship's Name SS/MIS "ST. AGNES".

Port FALMOUTH. Rpl. No. 14871.

When anchors or cables are supplied or retested, the following particulars are required:

Fee Letter if diff. from Equipment Letter	Equipment Letter
ANCHORS	CHAIN CABLES

ANCHORS

CHAIN CABLES

[illegible]

Have test certificates of new or retested equipment (if now supplied) been checked and endorsed? Yes.

Note:—Where anchors or chain cables are lost or condemned and renewed or supplied the corresponding test certificates should be cancelled by the Surveyors.

Surveyor to Lloyd's Register of Shipping

L. A. TURRELL.

0195^{2/2}

© 2021

Lloyd's Register
Foundation