

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

SHIP'S NAME "SAINT HONORAT" REPORT Lgs. No. 1283  
JD.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

For previous history of this case  
see Endorsement dated 7.4.55.

An unauthorised Special Survey which was held on this ship by a Surveyor appointed by Lloyd's Agents at Dakar in 12,54 has not been accepted by the Committee, but postponement of the Special Survey until 12,55 was approved on the understanding that the Special Survey would be carried out by an Exclusive Surveyor to this Society.

The LAGOS Surveyor attended at Dakar in 6,55 but as his stay was limited to one day he was only able to commence the Special Survey and hold a General Examination to confirm the agreed postponement until 12,55.

The Surveyor reports (6,55) that the ship was examined afloat and the requirements of a General Examination complied with and the Special Survey commenced. Various repairs were recommended, and a letter dated 1.9.55 has been received from Lloyd's Agents stating that these have been dealt with under the supervision of their Surveyor.

The Surveyor also reports that a number of shell and deck plates will require to be renewed by completion of the Special Survey. He also states in a letter dated 22.6.55 that no cargo battens are fitted.

The following items may be credited towards the Special Survey:-

EXAMINATION OF:- Holds,  
Machinery spaces,  
After F.W. tank.


SUBMITTED ACTION be DEFERRED for  
completion of the Special Survey by 12,55.

As Now.

ENDORSEMENT OF CLASS(B).

Shell plates No.2 sheerstrake and  
Nos.2 & 3 in 1st below (p.s.)  
slightly indented.  
Indents in poop side plating.

INSERT IN R.B.  
N.S.



© 2021

Lloyd's Register  
Foundation

012527-012536-0145