

5th October, 1963


M.S. "KOHOK MARU"

I have to report hereby the safety valve on the  
exhaust gas economizer has been adjusted under steam as  
follows.

Beginning of blow;

7 Kg/cm<sup>2</sup> on boiler pressure.

Chief Engineer

  
N. TAMAGAWA



© 2021

Lloyd's Register  
Foundation

012542-012548-0185