

LLOYD'S REGISTER OF SHIPPING

FOUNDED 1780


RE-CONSTITUTED 1834

Certificate of Class

Motor Tanker "SOUTHERN CLIPPER"
Official Number 9814 Port of Registry Malmo
Owners Rederi A.B. Clipper (Einar Hansen, Manager).
Builders, and where and when built Kockums Mek. Verkstads A.B. Malmo, January 1958.

REGISTERED TONNAGES
Gross 13,069
Net 7,584


MOULDED DIMENSIONS
Length 526' 8"
Breadth 71' 9½"
Depth 40' 1"


This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 14th January, 1958 in a fit and efficient condition as is prescribed by the Society's Rules for the safe carriage of dry and perishable or other approved Cargoes, and has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character  100A1 Carrying Petroleum in bulk subject to Periodical Surveys as required by the Rules.

The approved minimum freeboards from the deck line are as follows:—

Tropical	1730 feet mm inches (T).	Winter	} 2256 feet mm inches (WNA).
Summer	1926 feet mm inches (S).	North Atlantic	
Winter	2122 feet mm inches (W).	Allowance for fresh water for all freeboards	} 207 mm inches

Witness my hand,


Secretary.


Chairman.

71, Fenchurch Street, London, E.C.3. 4th March, 1958.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors or other Officers or Agents of the Society.”



Lloyd's Register
Foundation



© 2021

Lloyd's Register
Foundation

012585-012590-0003