

Steel /

(Req. 1a.)

(Received at London Office..... 19.....)

No. 199 Place Malindi Date May 16th 19 52

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to Specially Survey during Construction the Hull, Engines and Boilers of the Vessel No. 394 building by Messrs. Kockums Mekaniska Verkstads A.B. for Messrs. Iberia Compania Maritima S.A. Panama of 13000 Gr. Tons. Length 525'-0", Breadth 78'-0", Depth 40'-1" intended to be Classed *100A1, "Carrying petroleum in bulk"

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connection therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Engine Makers A.B. de lavals Angturbin and Kockums Meks. Verkstads AB

Boiler Makers Furth Wheelers Corp. and " " "

*Auth
27/5/52*

Signature.....

KOCKUMS 2021
Knut H. Holm

To the Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street, London, E.C.3.

NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—

"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

012585-012590-0015

heating coils, where fitted, have been satisfactorily pressure tested.