

carrier badly worn and lower pintle sleeve scored vertically (10mm width, 105 mm length, 2.5mm dep  
and steel plate (10.3 mm thick) welded and lower bea

Received from Chief Ship Surveyor

13 FEB 1961

SHIPS NAME "HOEI MARU" REPORT KOB No. 8571  
EA

Outstanding Conditions of Class: NONE

S.R.L. Appendix. (As before ~~or None~~)

Nature of Present Survey: ~~(Affloat and~~ in dry dock)

Repairs to rudder carrier and  
pintle, (cause not stated).


Recommendation:

IT IS SUBMITTED the ship is eligible to  
continue as classed and have record of  
DS 12,60 assigned as recommended, subject  
to rudder carrier and rudder lower pintle  
sleeve being specially examined by the  
Special Survey.

DS 12,60 Subject.

IN S.R.L. APPENDIX  
(Main structure partly of P.403 Steel).

Blk (new)



© 2021

C.S.S. Records Dept.

to file.

Lloyd's Register  
Foundation



012585-012590-0137