

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

3rd March, 1960.

(11) - assn (S)
AH/BS

Dear Sirs,

Motorship "STECKENPFERD"

Reverting to my letter of the 13th January, I shall be glad to learn whether you are now in a position to state where and when the Donkey Boiler Survey will be carried out and the ship submitted for inspection in dry dock.

I would also point out that the Continuous Survey of the machinery is very much behind-hand and arrangements should be made for this survey to be brought up to date as soon as possible. Your proposals in this respect are also desired.

The Society's Surveyor at Istanbul has reported that the vessel was under survey in January when temporary repairs were carried out to holed stem plating stated to have been damaged by contact with ice. It is understood that this damage is to be permanently repaired at Wismar but, as you are aware, the Society is not represented at that port. In the circumstances, if the repairs are carried out at Wismar, please let me know where and when an opportunity will be afforded the Society's Surveyors to examine the repairs in order that we may establish that they have been carried out in accordance with the Society's Rules.

If the repairs are not carried out at an East German



Lloyd's Register
Foundation

01291-01297-0088 1/2

2.

3rd March, 1960.

port, please let me know where and when the work will be done so that the Surveyors concerned may be advised.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

Messrs. Deutsche Seereederei,
Lange Strasse 6,
Rostock,
Germany.



© 2021

Lloyd's Register
Foundation

0058 $\frac{2}{2}$