

COPY OF AIR LETTER

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Your Ref:11/64

22nd June 1965

C.

RLT/BN

Dear Sirs,

M.S."SILVER BAY"

When this ship was at Tamano in March/April last the Surveyor reported that the water box of the auxiliary condenser was found to be wasted and this was temporarily repaired. It has been recommended that this item be renewed by the end of March 1966.

The ballast pump suction valve chest was found to be worn also and temporary repairs were effected. It has been recommended that this item be renewed by the end of March 1966.

The windlass gypsy wheel was found somewhat worn and it has been recommended that this item be renewed next drydocking by April 1966.

Fresh records of DS 3.65, TS 3.65 and ABS 3.65 have been assigned and class has been continued subject, inter alia, to the above matters being dealt with as recommended.

Yours faithfully,

pro Clerk to the  
Classification Committee.

Messrs. Valles Steamship Co. Ltd.,  
803, The Chartered Bank Building,  
HONG KONG

© 2021

Lloyd's Register  
Foundation

012591-012597-0257