

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "IRISH ELM" Rpt. Dub. No. 6171

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

LMC due 4.45 now held.

BS due 2.45 now held.

S due 4.47 now examined.

Minor repairs effected to the main and auxiliary machinery and electrical installation.

An additional, auxiliary, condenser fitted.

Ballast pump renewed.

All plain tubes in the port boiler renewed.

IT IS SUBMITTED that this vessel is eligible  
for the Record @ LMC 9.46,  
S 8.46.

J. S.  
14. 10. 46.



© 2021

Lloyd's Register  
Foundation

012606-012609-0036