

25 AUG 1919

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "COLLINGHAM". Report Cff. No. 41501

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/32.)

Nature of Survey

When due

The Cardiff Surveyors report the vessel has been placed in dry dock, bottom cleaned and coated and the special survey No. 2, due 1.18 and partly held, completed.

On account of wear and tear the plating under the donkey boiler has been repaired, bow plating, found to be slightly fractured in way of the lower stringer, repaired by doubling, and minor repairs effected.

Damage through striking a bank at St. Nazaire has been repaired as follows:- 2 shell plates removed, faired and refitted and 2 faired in place, lower part of stem removed, faired and refitted:

It is submitted the vessel appears worthy to remain as classed with record of survey 8.19 and notation of s.s. Cff. No. 2-19.

100 A-1.

8.19 Cff

2-19 Cff



© 2021

Lloyd's Register  
Foundation

23. 8. 19.

012606-012609-0049