

2 MAY 1958

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME Aclux..... REPORT VEN. No. 139

ES due 10.58, now held  
MBS due 8.57 .. ..  
TS due 9.57 .. ..  
SPS due 9.58 .. ..  
Conversion to OF burning.  
Docking.

SRL Surveyor reports defect in governor of aft dynamo engine and recommends its being placed in order by 10.58.

It is submitted that this vessel is eligible for THE RECORD.

ES 3.58  
MBS 3.58  
TSCL 3.58  
SPS 3.58, subject as now recommended.


B to note  
OF 3.58

Noted for Header



J.C.

© 1 MAY 1958



Lloyd's Register Foundation

012610-012612 0020