

4E

16 APR 1954

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

S NAME..... TRANSKIPPER..... REPORT Yka..... No. 2813.....

Damage to propeller blades, and it is recommended that the propeller be specially examined at the next dry docking.

IT IS SUBMITTED that this vessel is eligible to remain as CLASSED, subject as now recommended.

JL.

14.4.59.



© 2021

Lloyd's Register
Foundation

012624-012630-0092