

WEBER

DIPL. ING.

ISEIGATAN 15
HELSINGFORS
TEL. 442921 & 446405
TELEGR. WEBERS

L.77/61

HELSINGFORS, 27th January, 1961.

The Secretary,
Lloyd's Register of Shipping,
71. Fenchurch Street,
LONDON, E.C.3

RECEIVED

30 JAN 1961

And

Dear Sirs,

m.v. "MOSKVA"
Reports No. 6958 and 7037.

Your letter Classn.(S)/11.1.61 thankfully received.

Re. Report No. 6958, your letter Classn.C of 27.5.59:-
I confirm that the span of the crankshaft bearings is 548 mm.
- 570 mm was an error.

Re. Report No. 7037, your letter Classn.C of 30.5.70:-
There are two crankcase explosion relief devices their total
area being 400 cm^2 .

I remain, Dear Sirs,
Yours faithfully,

J. Weber



© 2021

Lloyd's Register
Foundation

012638-012646-0060