

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 { Overseas: Commi tee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

9th March, 1965.

R
NAB/CB

Dear Sirs,

s.s. "INCHCASTLE"

To complete the Boiler Survey, due at the end of October last, for the record MBS 11.64, the starboard boiler remains to be examined and its safety valves adjusted under steam, also the oil burning system and remote controls examined. The Owners state that this inspection will be completed at your port this month, and I shall be glad if you will give the case the necessary attention.

The vessel's class is subject, inter alia, to the forecandle deck plating being specially examined and dealt with as necessary and to permanent repairs being effected to shell plates H.7, G.14 and 15 (starboard side from aft) by the end of next month.

Yours faithfully,

Clerk to the
Classification Committee.

The Surveyors,
ADELAIDE.



© 2021

Lloyd's Register
Foundation

012663-012668-0106