

THROUGH HONG KONG
COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

26th February, 1965.

C
MWK/CB

Dear Sirs,

Steamer "INCHCASTLE"

This ship was surveyed at Rangoon during January on account of damage stated to have been caused by fouling the chain cable.

As a result of this survey class has been continued subject to the forecastle deck plating being specially examined and dealt with as necessary, and to permanent repairs to shell plates H.7, G.14 and 15 (starboard side from aft) being carried out before the end of April, 1965.

In order to complete the Main Boiler Survey, which became due at the end of October, 1964, the starboard boiler requires to be examined, its safety valves adjusted and the oil burning system and remote controls examined. I shall be glad to learn what arrangements you propose to make to complete this survey.

Yours faithfully,

pro Clerk to the
Classification Committee

Messrs. Williamson & Co. Ltd.,
P. & O. Building,
(G.P.O. Box 41),
Connaught Road,
HONG KONG.



© 2021

Lloyd's Register
Foundation

012663-012668-0108