

Ship's name

"INCHCASTLE"

Port

Rgn

No.

2633

Class is subject to

For conditions of class see previous
endorsement.

Last survey date 28.1.65

S.R.L. Appendix (as before ~~or none~~)

Nature of present survey (afloat ~~and in drydock~~)

Damage due to fouling chain cable involving forecastle
deck plating - temporary repairs. See also cable dated
28.1.65 for extension of limit.

Recommendation


SUBJECT to forecastle deck plating
being specially examined and dealt
with as necessary and to permanent
repairs to shell plates H.7, G.14 & 15
(s.s. from aft) by 4,65.

As Now. Subject

Amended.

IN S.R.L. APPENDIX.

Indents in shell plating (p & s).



© 2021

Lloyd's Register
Foundation

012663-012668-0110