

22 JAN 1965

Ship's name

"INCHCASTLE"

Port

Yka.

No.

5623

Last survey date 2.12.64

GB

Class is subject to

permanent repairs to shell plates
H.7, G.14 & 15 (s.s. from aft) by 1,65.

S.R.L. Appendix (as before ~~xxxxxxxx~~)

Nature of present survey (afloat ~~xxxxxxxxxxxxxxxx~~)

Temporary repairs to part deferred item as above.

SUBJECT as above.

Recommendation

As Now. Subject

IN S.R.L. APPENDIX.

Indents in shell plating (p & s).



© 2021

Lloyd's Register
Foundation

13/1-65