

THROUGH HONG KONG  
COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex  
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

5th July, 1962.

Dear Sirs,

Steamer "INCHCASTLE"

As a result of surveys held by the Society's Surveyors at Kobe in May the Committee have continued the class subject to shell plate in 4th below sheer (starboard side) in way of No.4 hold (part doubled) being examined and dealt with as necessary at the next drydocking and to the centre boiler not being used until repaired.

At that time the Main Boiler Survey was commenced and it was stated that this survey would be advanced on the ship's arrival in Canada where she was proceeding direct.

Yours faithfully,

c.c. Hong Kong

Deputy Clerk to the  
Classification Committee.

Messrs. Williamson & Co., Ltd.,  
P. & O. Building,  
(G.P.O. Box 41),  
Connaught Road,  
HONG KONG.



© 2021

Lloyd's Register  
Foundation

012663 - 012668 - 0123