

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

2nd November, 1962

C
DHGK/RW

Dear Sirs,

Steamer "INCHCASTLE"

Before your Report No. 22612 receives consideration, I have to point out that your recommendation to the Committee does not agree with that contained in the body of the Report, and you should issue an amended Interim Certificate with a notation of M.B.S. (port and starboard) 9.62, while in respect of the Donkey Boiler (165 lbs.) a fresh notation will be assigned when this boiler has been repaired.

It is noted from a Kobe Report dated May, 1962, that the depth of the wasted area of the furnaces is approximately 8 m.m., which is half the original thickness, and you should state from where the pressure of 165 lbs. was derived.

You should also confirm that the centre or donkey boiler has been disconnected from the main steam range.

Yours faithfully,

Deputy Clerk to the
Classification Committee

The Surveyors,
MIDDLESBROUGH



© 2021

Lloyd's Register
Foundation

012663-012668-0124