

E WEBER

DIPL. INS.

USEOKATU 15

ELSINKI

UH. 442921 & 446405

A.H.K. WEBERS

L.835/61

HELSINKI, 29th December, 1961.

The Surveyors,
Lloyd's Register of Shipping,
Järntorget 3, Street,
GÖTEBORG S.V.

Dear Sirs,

Icebreaker "LENINGRAD" Yard No.366.

I herewith enclose the reports No. 8382 M/Rpt.4d and No.8382 El./Rpt.13, which I hope Mr. J. Gardiner will find in order, enabling him to add his signature to same.

Regarding the Rpt.4d, page 1, "Overload and Short Circuit Protection", I have asked Mr. Wirtanen regarding the notation "S.C.450%". He states that this is correct. In the report for "Moskva" there was the same notation.

Concerning the Rpt.13 it turned out to be quite a lot of alterations made to the cables. I therefore enclose the following drawings which represent the situation on board the "LENINGRAD":- 2 A 22, 2 A 23, 2 A 24, 2 A 25, 2 A 26, 2 A 27, 2 A 28 and 2 A 29.

Ref. to your letter of 18.11.61 I note the amount Sw.Kr. 2,034,- due to the Gothenburg Office, which amount I will observe when now handing our Invoice to Messrs. Sandvikens Skeppsdocka.

Kindly forward the both reports and the drawings to the Head Office. Copies of the corresponding certificates will be posted directly from here.

Yours faithfully,

Drawings are sent in
separate cover.



Lloyd's Register
Foundation

012705 - 012710 - 0083