

COPY

LLOYD'S REGISTER OF SHIPPING



Port.....Odense.....

Date.....12th August, 1965.....

This is to Certify *that I have surveyed part of the machinery of the m.s. "INDIAN REEFER" 2600 gross tons of Esbjerg for continuous survey of machinery whilst lying on pontoon and afloat at Svendborg Skibsvarft A/S on the 23rd June, 1965 and subsequently and afloat at Sønderborg. and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned* **CSM 8.65**

Parts now examined:—

Docking. Propeller outside fastenings.
 Stb. Main engine No. 6 crankpin, bearings & pin
 Port & Stb. Intermediate shafts & bearings
 Port & Stb. Holding down bolts & chocks.
 Port & Stb. M.E. fuel oil injection & pumps
 Port & Stb. crankcase doors & explosion relief devices.
 Port & Stb. M.E. tested under working condition.

Auxiliaries:

Stb. aft. bilge pump. Port M.E. lub. oil pump. P. aux. eng. FW cool. water pump. Stb. aux. eng. SW cool. water pump. Pumping arrangement. P. & Stb. M.E. lub. oil coolers. Aux. air receivers & safety devices. Starting air pipes. Main air receiver & safety devices. P. aft. starting air compressor coolers & safety devices. Fire extinguishing arrangement. Steering machinery. Windlass. Electrical equipment.

B. Dalgaard
 Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150° F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."