

6 JUL 1964

Ship's name ["]MS INDIAN REEFER["]

Port ODENSE

No. 21032

Last survey date

Class is subject to

4.6.64

port forward outboard aux. engine
entablative (Metalock repaired 10.62 + 4.63) being
re-examined by 9.64.

Docking - wear down P 5.5 mm S 4.0 mm.
re-wooded to P 1.0 mm S 1.0 mm.

Above subject item now examined & surveyor
recommends re-examination before the end of
June 1965 (12 months limit).

Surveyor reports port main engine nos 5 & 6 main
bearing lower halves reinstalled.

Port aft no 1 & port forward no 3 generators completely
overhauled.

2.7.64

Classified 6.64 now & CSU (with date) when the survey has
been completed & subject as above & now amended.