

THROUGH COPENHAGEN  
COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
                          { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

15th October, 1963

C  
DHGK/MRN

Dear Sirs,

M.S. "INDIAN REEFER"

When this vessel was Lyttelton on the 5th September last, the Metalock repairs to the port forward outboard auxiliary engine entablature were examined and found to remain efficient.

It was recommended that these repairs should be re-examined by the end of September 1964, and class has been continued subject to this matter being dealt with by the time stated.

Yours faithfully,

pro Clerk to the  
Classification Committee

Messrs. J. Lauritzen,  
Hammerensgade 1,  
Copenhagen K,  
DENMARK.



© 2021

Lloyd's Register  
Foundation

012705 - 012710 - 0244