

11 OCT 1963

Ship's name *INDIAN REEFER* Port *LITTLETON* No. *5575*

Class is subject to Last survey date *5.9.63*

*Port forward outboard aux. engine entablature  
(HOTALOCK) repaired 10.62 and 4.63) being re-examined  
by 10.63.*

*SKL item now examined - and Surveyor  
recommends re-examination by 9.64.*

*It is submitted that this  
vessel is eligible to remain  
as CLASSED. Subject as above as  
now amended.*



© 2021

*11.10.63.*

Lloyd's Register  
Foundation