


COPY

LLOYD'S REGISTER OF SHIPPING



Port of VANCOUVER, B. C.

10th September, 1962.

This is to Certify that I have

Surveyed the Machinery of the M.V. "INDIAN REEFER" 2600 tons gross of Esbjerg as she lay afloat at Vancouver, B.C. on the 7th September, 1962 on account of Damage to the No.2 Port Forward Outboard Auxiliary Engine stated sustained on the 7th Sept., 1962

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book

No alteration

and that her Machinery Classification Record be continued in the Book, subject to the Port forward outboard auxiliary engine being further examined and dealt with as found necessary before the vessel leaves the West Coast of North America.

Parts now examined:

(C.S. Items only)

T. TAYLOR

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,5,60 (MADE AND PRINTED IN ENGLAND)

012705-012710-0255