

## LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

10 FEB 1954

## ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name " INDIAN REEFER " Official No. -

Port of Registry Ebsjerg

This ship has been under survey at Hamburg

on 23rd January, 1954 and subsequently 195 and the following alterations to the conditions of assignment of loadlines have now been effected/~~found~~:-

Two additional cargo ports have now been fitted in way of No. 1 tween deck on port and starboard sides between frames 137 - 139.


4'-8" x 3'-10", FITTED WITH RUBBER PACKING, & BUTTERFLY HANDLES  
EFFICIENT RIVETED DOUBLING PLATES  
FITTED. (SEE RPT. 8, 5/2/54)

Friedrich Ohlgen.

S

26 FEB 1954

A copy of this Report has been placed on board.



© 2021

Lloyd's Register  
Foundation

012705-012710-02811