

COPY

LONDON

LLOYD'S REGISTER OF SHIPPING



G-10348

Port Nagasaki

17th April, 1963

This is to Certify that I have surveyed part of the machinery

of the N.V. "KOTEI MARU" 9096 Gross tons of Kobe

for Continuous Survey of Machinery, Docking condition and propeller damage stated to have been caused by touching the bottom on the 25th February 1963 at Philadelphia during manoeuvring the vessel, whilst the vessel lay in drydock and afloat at Nagasaki on the 8th April 1963 & subsequently

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned CSM (with date) when the survey has been completed and TS(CL) 4.63.

Parts now examined:—

CSM

Main engine:—

- No. 3 cylinder, cover, piston & rod, valves & gears.
- No. 3 connecting rod, top end & guides.
- No. 3 crankpin & bearing.
- No. 5 & 7 journals & bearings.

Forward & aft turbo chargers.

Auxiliary blower (motor driven) (partial deck in E.R. S. aft)

Nos. 5 & 6 intermediate shafts & their Nos. 9, 10, 11 & 12 bearings.

Outb'd main S.W. cooling pump (S).

General service pump (P).

Bilge pump (P).

Y. Kojina **P.T.O.**

Surveyor to Lloyd's Register of Shipping

Y. Kojina

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150°F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



