

-2 APR 1965

Ship's name "CUTRAL CO."

Port B.A.S

No. 37380

Last survey date 15.2.65

Class is subject to :-

1. Forward scavenge blower rotor being dealt with as necessary by 5/65.
2. M/E No. 5 cylinder cover being specially examined by 5/65. (6 months).

Boiler damage
ABS due 2/65 comm 2/64 not advanced

The surveyor reports an explosion in the Stbd boiler furnace lighting up and inboard casing side wall buckled & brickwork displaced. Repairs deferred to end of March.


The boiler subsequently examined under hydraulic test and found tight. Casings & brickwork now repaired. Submitted condition recommended for boiler not to be used until repaired can now be deleted.

It is submitted that this vessel is eligible to remain as **CLASSED**. subject as above.

GJ
1/4/65

Owners should be asked to complete the ABS for record of 2.64 by examination of undernoted items.

To complete ABS:- EG boiler SV to adjust under steam



© 2021

Lloyd's Register
Foundation