

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

27th January, 1965.

C
AH/SO

Dear Sirs,

m.s. "CUTRAL CO".


Before your Report No.2296 receives the consideration of the Committee, I have to inform you that according to the records in this Office, feed water tanks are fitted on the second 'tween deck at the aft end of the machinery space adjacent to the aft peak bulkhead also that fresh water tanks are fitted in way of the top of the feed water and aft peak tanks and there is a drain tank in the double bottom at the aft end of the engine room.

It is concluded that these tanks have been dealt with for Special Survey, but your confirmation of this is desired. You should also confirm that the forward and after cofferdams have been tested and you should furnish a Rigging Report as required by Instructions to Surveyors Part 3A Page 35 Paragraph 33.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

The Surveyors,
MONTEVIDEO.



Lloyd's Register
Foundation

012711-012715-0203